

23-24, Yashodeep Heights, Plot No. 14/15, Sector 29C, Rabale-Ghansoli Node, Navi Mumbai - 400 701, INDIA. Phone: +91 93244 69890 Email: lab@gvmtesthouse.com www.gvmtesthouse.com



TESTING TRAINING

AUDITING

Date: 27.09.2023

Page No. 1 of 1

Test Order Ref: GVM/COATING/03928-1-2/08/2023 ULR: TC906123000002138F

## JSW PAINTS PRIVATE LIMITED

Vasind Village – Vasind, Taluka - Shahapur, Vasind, Thane, Maharashtra -421604

## **TEST REPORT ON BERGER SILK GLOW**

Source of Sample	•	Comple Supplied by the Customer	
· · ·	•	Sample Supplied by the Customer	
No. of Product tested	:	01 (One Only)	
Customer's Reference	:	PO No. VSND/2010014020/SER/R/2620007590, dt18.08.2023	
Condition of Sample	:	Satisfactory	
Date of Receipt	:	04.08.2023	
Lab Reference Number	:	2023/AUG/03928-1-2	
Sample Identification #	:	Berger Silk Glow	
Coverage #	:	110 sqft/Lit in 2 coats with 40 % dilution of water	
Curing Condition #	:	14 days @ 23 ± 2 °C & 65±5% RH	
Period of Test	:	04.09.2023 to 19.09.2023	

## **TEST RESULTS:**

S. N.	Test Conducted	Unit	Test Results	Test Method
1	Crack Bridging Ability	mm	0.44	EN 1062-7(A): 2004

# As furnished by the customer.

Note: 1. The results relate only to the items tested.

2. Report shall not be reproduced except in full, without the written approval of lab.

3. Any correction invalidates this report.

## For GVM TEST HOUSE AND RESEARCH CENTRE





