



23-24, Yashodeep Heights,
Plot No. 14/15, Sector 29C,
Rabale-Ghansoli Node,
Navi Mumbai - 400 701, INDIA.
Phone: +91 93244 69890
Email: lab@gvmtesthouse.com
www.gvmtesthouse.com



TC-9061

GVM TEST HOUSE
AND RESEARCH CENTRE

TESTING | TRAINING | AUDITING

Test Order Ref: GVM/COATING/03928-1-1/08/2023
ULR: TC906123000002137F

Date: 27.09.2023
Page No. 1 of 1

JSW PAINTS PRIVATE LIMITED
Vasind Village – Vasind,
Taluka – Shahapur, Vasind,
Thane, Maharashtra -421604

TEST REPORT ON BERGER SILK GLAMOUR

Source of Sample : Sample Supplied by the Customer
No. of Product tested : 01 (One Only)
Customer's Reference : PO No. VSND/2010014020/SER/R/2620007590, dt. -18.08.2023
Condition of Sample : Satisfactory
Date of Receipt : 30.08.2023
Lab Reference Number : 2023/AUG/03928-1-1
Sample Identification # : Berger Silk Glamour
Coverage # : 110 sqft/Lit in 2 coats with 40 % dilution of water
Curing Condition # : 14 days @ 23 ± 2 °C & 65±5% RH
Period of Test : 04.09.2023 to 19.09.2023


TEST RESULTS:


S. N.	Test Conducted	Unit	Test Results	Test Method
1	Crack Bridging Ability	mm	0.49	EN 1062-7(A): 2004


As furnished by the customer.

- Note:
1. The results relate only to the items tested.
 2. Report shall not be reproduced except in full, without the written approval of lab.
 3. Any correction invalidates this report.

For GVM TEST HOUSE AND RESEARCH CENTRE


GVM TEST HOUSE
AND RESEARCH CENTER

DINESH BURDE

Authorized Signatory


GVM TEST HOUSE
AND RESEARCH CENTRE

Regd. Office:

402, Yogesh Apartment CHS, Plot No. 26, Sector 8A, Airoli, Navi Mumbai - 400 708, INDIA.
GSTIN: 27BPBPB4090Q1ZM



ISO 9001:2015 Certified