



23-24, Yashodeep Heights,
Plot No. 14/15, Sector 29C,
Rabale-Ghansoli Node,
Navi Mumbai - 400 701, INDIA.
Phone: +91 93244 69890
Email: lab@gvmtesthouse.com
www.gvmtesthouse.com



ISO 9001:2015 Certified

GVM TEST HOUSE
AND RESEARCH CENTRE

TESTING | TRAINING | AUDITING

Test Order Ref: GVM/COATING/03927-4-1/08/2023

Date: 27.09.2023

Date of Receipt: 30.08.2023

Page No. 1 of 1

JSW PAINTS PRIVATE LIMITED

Vasind Village – Vasind, Taluka – Shahapur, Vasind,
Thane, Maharashtra -421604

TEST REPORT ON STAIN RESISTANCE

Source of Sample : Sample Supplied by the Customer
No. of Product tested : 01 (One Only)
Customer's Reference : PO No. VSND/2010014020/SER/R/2620007613, dt. -27.08.2023
Condition of Sample : Satisfactory
Lab Reference Number : 2023/AUG/03927-4-1
Sample Identification # : Asian Paints Royale Glitz
Period of Test : 06.09.2023 to 08.09.2023
Test Method # : ASTM D 4828-1994

TEST RESULTS:

S. N.	Stain Name #	Nos. of Wash Cycles	Evaluation of the condition of Stain after wash cycles
1	Pencil	100	10
2	Shoes Polish	100	10
3	Tea	100	10
4	Coffee	100	7
5	Highlighter	100	7
6	Crayon	100	10
7	Tomato Ketchup	100	10
8	Lipstick	100	7
9	Mud	100	10
10	Turmeric	100	5

Rating Scala as per ASTM D 4828

- 0 - No change from original intensity (depth) of stain
- 3 - Slight change from original, but readily visible
- 5 - Moderate change from original, slightly visible, and
- 7 - Large change from original, barely visible
- 10 - All Stain removed

As furnished by the customer.

- Note:
1. The results relate only to the items tested.
 2. Report shall not be reproduced except in full, without the written approval of lab.
 3. Any correction invalidates this report.

For GVM TEST HOUSE AND RESEARCH CENTRE


GVM TEST HOUSE
AND RESEARCH CENTER
DINESH BURDE

Authorized Signatory



Regd. Office:

402, Yogesh Apartment CHS, Plot No. 26, Sector 8A, Airoli, Navi Mumbai - 400 708, INDIA.
GSTIN: 27BPPBPB4090Q1ZM